

Table of Contents

Theme I

Case Histories in Foundations of Structures and Failure Records

Failure of the Ghana Law School Building in Accra, Ghana	3
Lakeview Tower: Case History of Foundation Failure	7
Moisture Induced Damages to Building Foundations	5
Soil Conditions and Foundation Problems in the Desert Regions of the Middle East	1
Damaging Settlements of a Building due to Gypsum Dissolution	7
Bearing Capacity of Piles Under Long-Term Vibration	1
Settlement Observations on Two Mat Foundations	7
Caisson Design by Instrumented Load Test	1
Grouting to Control Deep Foundation Settlement	1
Performance of Large Diameter Oil Storage Tanks	1
Behaviour of Bridge Abutment on Fractured Chalk	7
Power Station Foundations in Deep Expansive Soil	7
Recovering Differential Settlements by Vertical Drains	7
Vertical Load Tests of Footings on Silt	3



Negative Friction and Lateral Loading on Piles E. E. De Beer, M. Wallays, E. Goelen—BELGIUM	. 101
Geotechnical Problems and Performance Studies - Chilla Power Scheme, Hardwar D. N. Bhargava, Dwarka Nath, S. N. Kapoor, Sunder Singh—INDIA	. 105
Settlement of a Building Founded on Difficult Soil	. 111
Ground Heave Due to Pile Driving	. 117
Geologic Considerations in Civil Constructions - Malaysian Case Studies	. 123
Observation and Analysis of Settlements of Oil Tanks on High Compressive Saturated Soft Clay	127
Evaluation of a Differentially Settled TankS. M. Gazioglu, J. L. Withiam—U.S.A.	133
A Combined Earth and Rock Bearing Foundation - Hospital Humana Mexico City D. F L. E. Wilson, Michael R. Stomer, Pablo Girault—U.S.A.	143
Tower Foundations Bearing Above Weak Soils	151
Foundation Design and Construction for a Large Mill Complex	157
Effect of Foundation Deformations on the Damage of a Masonry Villa (Case History)	165
A New Version of Rectification for the Leaning Structures and Foundations Yi-Ji Wang, Jian-Xin Yuan—CHINA	169
Deformation of Slopes of Two Excavations in Soft Clays C. W. Sheng—CHINA	173
Field Observation of Pore Pressure in Soft Clay	179
Settlement of a One Floor Building on Soft Clay Beside a Heavy Building	185
Prediction of Axial Pile Capacity Based on Case Histories	191
Foundation Performance of Very Old Structures	201



Philip Morris Corporate Headquarters Building	209
Chimney Foundation on Drilled Piers	217
Adjustable Columns Control Settlement of Structure	223
Design Considerations and Long-Term Performance of a Building Foundation in Clay	229
Monitoring and Performance of a Bridge Abutment	235
Foundation Problems and Solutions at the Bridge River, Powerhouse No. 1	241
Raymond Concrete Cylinder Piles in Arabian Gulf	249
Foundation Heave at ASCO II Nuclear Power Plant	259
Settlement Experienced at a Recently Licensed Nuclear Station	267
Tank Farm Construction Over Soft Organic Clays - A Case History	271
Embankment on Vertical Drains - Pore Pressures During Construction	275
Power Line Foundation Design Using the Pressuremeter	279
Non-Negative Skin Friction Piles in Layered Soil	285
Excessive Settlement in Buildings A. Verghese Chummar—INDIA	289
Structural Fill of Steel Slag Caused Heave of a Building	295
Theme II	
Case Histories in Retaining Structures and Failure Records	
Monitoring of a Deep Basement in London	. 301



Predicted and Observed Lateral Deformations of Anchored Retaining Walls	309
Tj. Kooistra, F. L. Beringen—THE NETHERLANDS	·
Stability Problems in a Deep Excavation in Clay	315
Field Experience on Corrugated Metal Culverts	325
Braced Cofferdam to Improve Spillway Stability During Rehabilitation	331
Repair of a Reinforced Earth WallLong, Livet, Boutonnet, Marchal, Olivier, Nabonne, Plaut—FRANCE	335
The Pathology of Metal Culverts	341
Behavior of Braced Cut in Connection with Construction of Large Underground Station S. Uchida, H. Ito, T. Kaino, H. Tarumi—JAPAN	347
Earth Pressure on Retaining Walls and Buried Pipes	355
Thrust Evolution on the Shoring of Two Large Excavations in Geneva	363
Field Behavior of Retained Earth Structure	371
Use of Ground Anchors in Residual Soils	377
Load Measurements of an Anchored Retaining Wall	387
Failure of an Anchored Sheetpile Bulkhead D. P. LaGatta, D. R. Shields—U.S.A.	393
Anchor Slab Retaining Wall Stands Overtopping FloodZ. L. Wang, X. M. Wu, Z. S. Zhang—CHINA	4 01
Performance of a 30 m Deep Instrumented Diaphragm Wall	405
Failure of a Small Gravity Dam and the Repair	411
Permanent Tieback Retention System	417



Theme V

Case Histories in Geotechnical Earthquake Engineering

J. R. Wagner—U.S.A.	425
Pile Foundation under Liquefied Soils Liu Huishan, Qiao Taiping—CHINA	433
Liquefaction Risk Evaluation During Earthquakes	445
Liquefaction Potential of a Silty Sand Site	455
Research on the Permeability and Earthquake Damage of An Earth Dam Foundation	459
Prediction of Pore Water Pressure During Earthquakes in Southern Kyoto Area F. Oka—JAPAN	469
A Geotechnical Study for Land-use Planning Purposes	475
Seismic Response and Liquefaction Analysis by an Approximate Method	481
Verification and Evaluation of the Result of Liquefiable Soil Treated with Vibroflotation Gu Bao-he, Hu Zong-han, Wang Wan-yu—CHINA	485
Seismic Motion Selection Criteria for Dam Design	491
Behavior of Some Earth Dams on Liquefiable Soil	499
Earthquake Damages to Earth Dams and Levees in Relation to Soil Liquefaction and Weakness in Soft Clays	511
Surface Damage of Tangshan Earthquake and Characteristics of Response Spectrum of Ground Movement	523
S. D. Zhao, H. Q. Fang—CHINA A Comparison of Methods of Estimating the Attenuation of Earthquake Strong Ground Motion	531
O. W. Nuttli, R. B. Herrmann-U.S.A.	
Assessment of Earthquake Size from Rock Fracture Dimensions of Seismic Source in Geotechnical Earthquake Engineering Investigations	535



Table of Contents

Theme III

Case Histories in Dams, Embankments and Slopes

Powerhouse Slope Behavior, Fort Peck Dam, Montana	541
J. V. Hamel, G. S. Spencer—U.S.A.	
Grand Coulee Riverbank Stabilization - Case History of the Design of Remedial Measures	553
J. Lawrence Von Thun—U.S.A.	
Peculiar Behaviour of the Manicouagan 3 Dam's Core	561
The Santa Helena Dam on Compressible Foundation	569
Vinod K. Garga, Arnoldo V. Rocha, Homero G. Ramos—CANADA	
Clay Shale Foundation Slide at Waco Dam, Texas	579
W. R. Stroman, R. R. W. Beene, A. M. Hull—U.S.A.	
The Use of Limited Field Observation in Remedial Design	587
J. P. Sully, G. I. McPhail—VENEZUELA	
Design and Performance of Horizontal Drains	593
J. H. Kleppe, G. M. Denby—U.S.A.	
Performance of Trial Embankment on Soft Clay	599
T. Shibata, H. Sekiguchi—JAPAN	
Embankments Built Over Swamps	609
Samuel Y. Ng, James C. RuddU.S.A.	
Stability of Slopes - A Case History	619
G. Ramasamy, Gopal Ranjan, Bhawani Singh, A. C. Khazanchi, U. N. Sinha—INDIA	
Performance of an Embankment on Peat	625
R. E. Olson—U.S.A.	
Stability of Hill Slopes and Foundation Condition at Radio Astronomy	
Centre Ootacamand	631
R. K. Katti, V. S. Chandrasekaran, A. Parthasarathy, K. K. Moza—INDIA	
An Embankment on Soft Clays with Sand Drains	637
A. Cancelli, A. Cividini—ITALY	
Controlled Breaching of a Full Scale Clay Flood Bank	645
A Maniand Linited Kinicham	



M. Fukuoka—JAPAN	655
Collapsible Soils Chashma Right Bank Canal	665
Failure of a Dredged Slope in a Sensitive Clay D. P. LaGatta, S. L. Whiteside—U.S.A.	671
The Delayed Failure of a Large Cutting in Hong Kong	679
The Failure of a Cut Slope on the Tuen Mun Road in Hong Kong	683
The Failure of a Soil Blanket Lining Caused by the Action of Bacteria	689
Failure Slope in Clay Shales in Aratu Bay - Brazil	695
Failure of an Embankment on Soft Clay	701
The Foundation of the Right Bank in Wadi-Zarat Dam	707
Lake Monona Causeway - Madison, Wisconsin, USA	713
Sealing Leakage of Earth Dam by Concrete Diaphragm	721
Behaviour of Ramganga DamsBhagwat V. K. Lavania—INDIA	725
Failure of Micaceous Waste Tailings Dam	731
Performance of a Stone Column Supported Embankment	735
Slide Stabilization with Gravel Trenches	743
Long Term Failure in Compacted Clay Slopes	749
P. C. Kotzias, A. C. Stamatopoulos, B. Karas—GREECE	755
The Stability of Shannon Embankments	759



Theme IV

Case Histories in Off Shore Structures

Rock Borer Attack on Juaymah Trestle Concrete Piles	767
2. 11. Walsie, W. C. Blown, R. Al-Shalel—SAUDI ARADIA	
Theme VI	
Case Histories in Machine Foundations	
Machine Foundations in Power Plant and Other Industries - Case Studies	775
Dynamic Response and Static Analysis of RCC Space Frames Supporting High Speed Centrifugal Machines with Coupled Soil-structure Interaction Dilip K. Chakravorty, Dhiman K. Ghosh, H. N. Batavyal—INDIA	781
A Case Study on Decreasing Vibration of Machine Foundations and Structures Wang Xikang—CHINA	787
Theme VII	
Case Histories in Rock Mechanics	
Shale Pit Slopes - A Case History	793
Stillwater Tunnel, Central Utah Project, Utah, Case History	807
Pittsburgh's Mt. Lebanon Tunnels - A Case History	817
Mechanised Rock Tunneling in Adverse Conditions	827
The Experience of a Dam Founded on Difficult Rock Foundation	833
The Stability of Underground Power Chambers in Brittle Rock	843
Geotechnical Problems in a Bridge over Corinth Canal	849
Research on Slope Stability of a Certain Open-Pit Mine	855



Theme VIII

Case Histories in Selection of Sites for Industrial Structures and Determination of Design Soil Parameters

Study on Vibration in Site Selection for a Precision Instrument Factory Pan Fulan—CHINA	. 863
A Dockwall Failure in Milwaukee, Wisconsin	. 869
A Case of Singular Geotechnical Failure for Industial Structures in the Peruvian Andes	. 877
Siting Study for Aluminum Plant in Central Kentucky	885
A Case of Land Use and Urban Planning in the Expansive-Soil District	895
Siting for a Nuclear Power Plant in Saudi Arabia	. 901
Guest Lectures	
Case Histories for Today's Geotechnique	907
Foundations on Friction Creep Piles in Soft Clays	913
Behavior of Two Big Rockfill Dams, and Design Aims V. F. B. de Mello—BRAZIL	923
Time Dependent Limit Stability of Tunnel and Dam Engineering in Difficult Rocks Tan Tjong Kie—CHINA	943
The Brenda Mines' Cycloned-Sand Tailings Dam Earle J. Klohn—CANADA	953



Table of Contents

Guest Lecture

A Case History of Bridge Performance During Earthquakes in Japan981
T. Iwasaki—JAPAN

Theme I

Case Histories in Foundations of Structures and Failure Records

Lateral Pile Response from Model Tests in a Large Centrifuge	1011
Down Drag on an Instrumented Bored Pile in Soft Clay	1019
R. K. Bhandari, M. R. Soneja, Devendra Sharma—INDIA	
Stability of Suspension Bridge Anchorage System	1027
Gopal Ranjan, Shamsher Prakash, Swami Saran, Bhawani Singh—INDIA	
Settlement of Three Grain Tanks on Alluvial Soils Exhibiting Desiccation Profiles	1033
Dynamic Precompression Treatment—A Case History	1041
Settlement Performance of a Mat Foundation on Unsaturated Loess	1053
Power Plant Construction on a Thick Sand Deposit	1059

Theme II

Case Histories in Retaining Structures and Failure Records



Theme III

Case Histories in Dams, Embankments and Slopes

Slip Failure of Embankment on Soft Marine Clay	1079
Evolution of Design and Construction of Lornex L-L Tailings Dam	1083
Efficacy of Grout Curtain at Ramganga Dam	1089
Earth Dams at Nuclear Power Plants	1093
Performance of Some Embankment Dams in India	1097
Reconsideration of Failure Initiating Mechanisms for Teton Dam	1103
Theme V	
Case Histories in Geotechnical Earthquake Engineering	
Liquefaction of a Soil Deposit During an Earthquake	1117
Assessment of Seismic Stability of Earth Dams by Comparative Methods	1123
Post-Earthquake Failure of a Tailings Dam Due to Liquefaction of the Pond Deposit Kenji Ishihara—JAPAN	1129
Theme Vi	
Case Histories in Machine Foundations	
Vibration Studies of Block Type Machine Foundations	1147
Forge Hammer Foundation on Dilative SoilS. J. Yang—CHINA	1155
Foundation-Rearing-Rotor Interaction Problem in Controlling Vibrations in a 120 mw Turbo-Generator	1157
Krishen Kumar, Shamsher Prakash—INDIA	



Theme VIII

Case Histories in Selection of Sites for Industrial Structures and Determination of Design Soil Parameters

Theme IX

Miscellaneous Case Histories

A Case History of Chemical Attack of a Clay Shale	1175
Design and Construction of a Railway Yard, Embankment and Foundations Under Difficult Groundwater Conditions	1183
Preloading for Large Storage Building	1191
Densifying a Landfill for Commercial Development	1195
Dykes on Clay Foundation at Bersimis 2	1201
Design of Road Cut Adjacent to Existing Structure	1209
A New Method of Stabilization of Soft Soils	1215
Ground Movement Characteristics Above Mined Panels in Appalachia - An Empirical Approach	1221
Performance of Preload on Cohesionless Soils	1229
Performance of Sand Drains in a Tidal Marsh	1235
Geotechnical Aspects of the Fort McHenry Tunnel - Design and Construction	1245



Case History on Dewatering Problems in Shanghai	1255
In Situ Stabilization of Two Industrial Sites by Dynamic Compaction	1259
The Behavior of House on Seasonally Frozen Ground	1265
Settlements Induced by Soft Ground Tunneling	1269
Unplanned Construction of a 210 Ft High Temple	1281
Slurry Trench Wall Replaces Structure Underpinning	1287
Ground Improvement for Oil Tank Farm in Indonesia	1297
Twenty-Year Performance of Soil-Cement Dam Facings	1307
Foundation Movement Monitoring of Heavy Structures - A Case History	1313
Dewatering of the Construction Site for a 200-Foot Diameter Clarifier Tank Founded on Sand and Gravel Grover C. Cox—U.S.A.	1319
Failure of Salt-Aragonite Storage Pad	1329
Performance of Diaphragm Walls in Deep Foundation Excavations	1335
Stabilization of the Oudenberg Hill in Geraardsbergen R. De Paepe, M. Wallays—BELGIUM	1345
Movements Around Transit Tunnels in Mixed Ground	1351
G. W. Lee, Jr., S. K. Bhatia, G. A. Swenson, III, S. P. Clemence—U.S.A.	1361
Improvement of a Dumped Rockfill Foundation by Dynamic Consolidation	1365
Upgrading Existing Footings with Micro-Piles	1373



Highway Interchange Constructed with Slurry Walls	1385
E. Itzig Heine, Frank A. McDonough, Surinder Singh—U.S.A.	
Construction of Key Lake Tailings Facility	1393
India's First Venture Relating to Subsurface Drainage by Horizontal Drains T. K. Natarajan, A.V.S.R. Murty, Deep Chandra—INDIA	1401
Uranium Mill Tailings Geotechnical Investigations—A Case History	1405
Dewatering, Hydraulic Failure and Subsequent Analysis of a Sheeted Excavation	1415
Expansive Soil Pavement Design Using Case Studies	1421
Soft Ground Tunnel Failures in Michigan	1429
Case History—Hyperbolic Cooling Tower Foundation	1435
Subsidence Affects Due to Gypsum Solution in Syracuse, New York	1439
Direct and Indirect Influence of Mining Related Subsidence on Structural Damages—A Case Study	1443
H. J. Siriwardane, L. K. Moulton—U.S.A.	
The Creation of Additional Space for the Storage of Dredged Materials— A Case History	1447
Nicholas Chryssafopoulos—U.S.A.	
Ground Response, Baltimore Lexington Market Tunnels	1451
Mechanism of Dynamic Consolidation and Its Environmental Effect	1459
Pretreatment of a Soft Soil by Surcharging—A Case History D. Lakner, I. K. Lee, E. Armstrong, O. G. Ingles—AUSTRALIA	1467
Instrumentation of a Sewer Tunnel in Weak Singapore Soils	1473