



Table of Contents

Volume I

Session I

"Case Histories of Geotechnical and Hydrological Management of Solid, Hazardous, and Radioactive Wastes"

	Page No.
W.C.B. Gates (USA)	Use of Deeply Weathered Rock as Landfill Cover Material, Patacon Landfill, Republic of Panama. 1.05 1
D. Raghu H.N. Hsieh (USA)	Disposal of Phenolic Waters from a Producer Gas Plant. 1.06 7
D. McGrane (USA)	Complementing Radiologic Data with Geology—A Case History. 1.07 13
W.M. Kilkenny (England)	A Low-Rise Hospital Development on Restored Opencast Fill. 1.08 19
J.A. Caldwell R.E. Rager L. Coons (USA)	Geotechnical and Groundwater Site Characterization on the Umtra Project. 1.09 25
D.E. Mills D.A. Cordell (USA)	Evaluation of Remedial In-Waste Lechate Head Reduction. 1.10 35
H. Dezfulian (USA)	Site Assessment and Remediation of an Oil-Producing Property. 1.11 43
D. Raghu R.J. Van Orden (USA)	Failure and Reconstruction of a Waste Containment Pond Slope. 1.13 51
M.D. Huag J. Atwater R.B. Knight P. Kozicki A. Lissey (Canada)	Implementation of Remedial Measure to Contain a PCB Spill. 1.14 55
P.J. Bosscher T.B. Edil (USA)	Performance of Lightweight Waste Impoundment Dikes. 1.17 63
G.H. Cramer (USA)	A Study of Contamination Migration at a Hazardous Waste Facility in Louisiana. 1.21 71
R.V. Sarsby (England)	Control of Uplift from Ground Water. 1.22 75
A.S. Burgess M.S. Leonard G.S. Laird (USA)	Design and Construction of a Soil Bentonite Slurry Wall Around an Operating Facility Superfund Site. 1.23 81



<i>Session I continued</i>		Page No.
G.S. Laird A.M. Gurevich W.B. Lozier (USA)	A Modified Field Infiltrometer Test for Clay Liners. 1.25	89
S.M. Testa (USA)	Hazardous Waste Disposal Site Hydrogeologic Characterization. 1.26	97

Session II
"Case Histories in Geological Engineering and Rock Mechanics"

S.C. Bandis (Greece)	Engineering Design of Rock Slope Reinforcement Based on Non-Linear Joint Strength Model. 2.03	107
J. Pitts (Singapore)	Stability of a Rock Slope at Bukit Batok New Town Singapore. 2.07	115
J.K.P. Kwong (USA) L.J. Endicott (Hong Kong) A.C. Lumsden (England)	Slope Stability Evaluation for an Existing Steep Cut in Weathered Volcanics Hong Kong. 2.08	123
N.M. Patel (India)	Distress in a Hill and Remedial Measures. 2.11	127
Z.Q. Wang R.X. Zhang (China)	Case Study—Ground Failures and Ruptures in Xian City. 2.12	131
G.A. Hu (China)	On a New Problem of High Speed Landslides. 2.13	137
K.D. Weaver D.J. Gross L.T. Bauer (USA)	Slope Stabilization Measures for Kirkwood Penstock, Early Intake California. 2.14	143
B. Prabhakar J.L. Jethwa B. Singh (India)	A Case History of Tehri Tunnels. 2.15	147
C. Rodriguez-Perez L. Vazquez Castillo C. Rodriguez-Molina A. Vazquez Castillo (Puerto Rico)	A Study of a Road Landslide in Puerto Rico. 2.16	151
Z.R. Fattohi (Iraq)	Simultaneous Velocity Measurements with Uniaxial Loading on Weak Sandstone from Iraq. 2.18	159



<i>Session II continued</i>	Page No.
A.C. Van Besien N.B. Aughenbaugh (USA)	Johnston City School, Mine Subsidence or Shallow Foundation Problem. 2.19 163
L. Jiayou M. Jianyun (China)	The Successful Construction of a High Gravity Dam on Complex Rock Formations. 2.20 167
M.G. Karfakis B.A. Suprenant (USA)	Ground Failure Investigation Over Abandoned Coal Mines: A Case Study. 2.21 173
R.K. Goel J.L. Jethwa B. Singh (India)	Case History of Maneri—Uttarkashi Power Tunnel. 2.22 177
J.G. Cabrera (USA)	Foundation Investigation and Treatment for the Main Dam, Itaipu Project. 2.23 185
D. Raghu D.A. Antes J.L. Lifrieri (USA)	Grouting a Water Tower Foundation in a Carbonate Formation. 2.24 195
R.D. Prager G.S. Grainger R.L. Butts (USA)	Rock Response in a 12-M Tunnel Through a Zone of Low Strength. 2.25 201
P.S. Khare S.G. Kulkarni S.L. Mokhashi (India)	Stability Check of Escarpment Using Finite Element Method. 2.28 207
A.K. Dube B. Singh (India)	Rock Mass Behaviour Assessment for Large Cavern in Rock. 2.29 211
J.A. Larson (USA) D.P. Richards (Turkey)	Support Over Cavities of Unknown Depth for Underground Facility. 2.34 215
R.C. Ilsley S.B. Fradkin E.F. Shorey (USA)	Evaluation of the Site Investigation and Construction Related Aspects of the Milwaukee Crosstown Deep Tunnel. 2.36 221
J.M. Descour R.J. Miller (USA)	Microseismic Activity in an Open Pit Lignite Mine. 2.37 229
A.O. Erol A.W. Dhowian (Saudi Arabia)	Foundation Failures Associated with Salt Rock and Surrounding Coastal Plain. 2.39 237



<i>Session II continued</i>	Page No.
G.S. Mehrotra R.K. Bhandari (India)	A Geological Appraisal of Slope Instability and Proposed Remedial Measures at Kaliasaur Slide on National Highway Garhwal Himalaya. 2.40 245
Y.P. Chugh K. Chandrashekhar R. Missavage (USA)	Subsidence Movements and Structural Damage Related to an Abandoned Coal Mine. 2.41 253
T. Ramamurthy V.M. Sharma (India)	Performance of Some Tunnels in Squeezing Rocks of Himalayas. 2.42 263
B. Hasan (Pakistan)	Effects of Geology and Geotechnical Properties of Rocks for the Selection of Type of Dams. 2.44 271
A.M. Jokhyo (Pakistan)	Slopes in Weak Rocks. 2.46 279
K.K. Kapoor S.C. Patodiya (India)	Construction of a Hydrel Power House in Weak Rocks. 2.47 285
M.C. Betournay C. Mirza K.C. Lau (Canada)	Coring of Soft Soil-Like Rock Materials. 2.49 291
K. Anguelov (Bulgaria)	The Great Landslides in the East-Maritza Open-cast Mines (Bulgaria)— A Theoretical Paradox in the Engineering Geology. 2.50 299
H.C. Nainwal Y.P. Sundriya C. Prasad (India)	Study of Some Debris Avalanches in Garhwal Himalaya, India. 2.52 305
R.S. Mithal (India)	Lithotectonic Landslides and Hazards in Parts of Garhwal-Kumaon Himalaya. 2.55 311
M.A. El-Sohby S.O. Mazen (Egypt)	Geotechnical Characterization of Subsoil Deposits at Cairo. 2.56 321
D.M. Pancholi K.E. Modhwadia P.H. Vaidya (India)	Geo-Engineering Problems in the Spillway Foundations and Their Treatment at Guhai Reservoir Project in Gujarat, India. 2.58 327
R.K. Bhandari (India)	A Novel Low Cost Drum Diaphragm Wall for Landslide Control in The Himalaya. 2.60 333
M. Christos (Greece)	Prevision of the Bearing Capacity of Superficial Foundation on Jointed Rock. 2.61 337
K. H. Earley D. Rudenko (USA)	Use of Geophysical Methods in a Geotechnical Investigation. 2.64 341



Session III
"Case Histories of Dams, Embankments, and Slopes"

	Page No.
D. Abolhassani F. Bahrami-Samani (Iran) R.P. Brenner (Switzerland)	Unusual Behaviour of An Earth-Rockfill Dam. 3.01 347
J.W. Erwin G.R. Baer (USA)	Seepage Incident, St. Stephen Powerhouse, St. Stephen, S.C. 3.04 355
T.K. Natarajan A.V.S.R. Murty D. Chandra (India)	Control of Surficial Slides by Different Erosion Control Techniques. 3.05 361
T.K. Natarajan P.J. Rao (India)	Restoration of the Stability of Retaining Wall. 3.06 365
Z.V. Solymar G.C. MacTavish W.G. Matthews (Canada)	Some Design Aspects and Performance of an Embankment Dam. 3.08 369
K. Kogure K. Matsuo (Japan)	Settlement Measurements of Peat Deposits as Embankment Foundation. 3.09 377
L. Knuppel F. McLean A. Roodsari (USA)	Underseepage Control Measures at Painted Rock Dam. 3.10 383
R.B. Smith W.O. Yandell (Australia)	Prediction and Field Performance of an Instrumented Road. 3.11 395
R.C. Findlay (USA)	Hydrostatic Pressure at a Soil-Structure Interface. 3.12 401
V.K. Singh B.D. Baliga B. Singh (India)	Openpit Mine Slope Stability—A Case Study. 3.13 407
H.J. Von M. Harmse F.A. Gerber (South Africa)	A Proposed Procedure for the Identification of Dispersive Soils. 3.14 411
Z.J. Ke C.H. Yong Y.H. Chang (China)	Failure and Repair of the Slope of Railway Embankments and Expansive Soils. 3.15 417



<i>Session III continued</i>	Page No.
M.C. Goel (India) D. Mudjihardjo (Indonesia)	Performance Evaluation of Rarem Dam. 3.16 423
M.C. Goel (India) A. Zainiko J.L. Surabaya (Indonesia)	Colbond Drains for Rapid Consolidation at Manggar Besar Dam. 3.17 433
K.V. Rupchang (India)	Problems and Behaviour of a Dam Founded on a Weak Zone. 3.18 437
D.G. Anderson J.G. Dehner T.B. King (USA)	Performance of a Harbor Embankment. 3.20 443
T. Smith C.E. Deal (USA)	Cracking Studies at Sand H Basin by the Finite Element Method. 3.21 451
J. Christodoulis H. Giannaros (Greece)	Failure of Railway Embankment. 3.22 457
H. Hejazi (USA)	Construction Problems with an Earth and Rockfill Dam. 3.24 461
J. Alberro G. Macedo L. Montanez F. Gonzalez-Valencia (Mexico)	Penitas Dam—In Situ Stress-Strain Characteristics of Materials. 3.26 467
M.D. Scott R.C. Lo E.J. Klohn K.K. Lum (Canada)	Overview of Highland Valley Tailings Storage Facility. 3.27 479
B. Bailey E. Bloom T.R. West J.A. Mundell (USA)	Excessive Seepage Losses at Westwood Lake Dam. 3.29 489
D.R. East J.W. Ransone W.A. Cincilla (USA)	Testing of the Homestake Mine Tailings Deposit. 3.30 495
J.R. Lambrechts E.B. Kinner (USA)	The Great Salt Lake Causeway—A Calculated Risk Revisited. 3.31 503



<i>Session III continued</i>	Page No.
J. Binquet U. Zappi (France)	Wadi Qattarah Dams Case History. 3.32 511
J.L. Llopis C.M. Deaver D.K. Butler S.C. Hartung (USA)	Comprehensive Seepage Assessment: Beaver Dam, Arkansas. 3.33 519
R.K. Katti D.R. Katti A.R. Katti (India)	Remedial Measures to Seepage and Instability Aspect of a Dam Near Bombay. 3.34 527
R.J. Termaat E.O.F. Calle R.O. Petschl (The Netherlands)	The Probability of Failure of an In Stages Constructed Embankment on Soft Soil. 3.37 533
J.A. van Herpen J. de Pee (The Netherlands)	Dike Reconstruction Polder Oudendijk. 3.38 541
J. Dekker (The Netherlands)	Evaluation of the Failure of an Important Dike in the Netherlands. 3.39 547
R.C. Chaney D.C. Tuttle (USA)	Coastal Bluff Retreat at Big Lagoon, California. 3.40 555
P.L.R. Pang Y.C. Chan (Hong Kong)	Investigation of Settlements of a Trunk Road Embankment in Hong Kong. 3.41 559
W.R. Stroman R.R.W. Beene P.D. Thornhill (USA)	Kerrville Ponding Dam, Guadalupe River, Texas. 3.42 567
Z. Shixuan (China)	A Case Study of Success to Structures Founded on Expansive Soils. 3.44 575
T. Sivapatham (Sri Lanka)	Behaviour of Inginimitiya Embankment Dam. 3.45 581
T. Mathur R. Willis (USA)	Performance of an Instrumented Earth Dam With Fat Clay Core. 3.46 587
B.D. Leonard J.M. Olsen (USA)	A Finite Element Analysis of the Utah "Thistle" Failure. 3.48 593



<i>Session III continued</i>	Page No.
F. Colleselli P. Simonini M. Soranzo (Italy)	Improvement of Mechanical Properties of Soft Soils by Use of a Pre-Loading Embankment. 3.51 599
T. Ramamurthy S.L. Jain (India)	Deformation Response of Some Earth and Rockfill Dams. 3.52 607
B.V.K. Lavania (India)	History of Tehri Rockfill Dam Design. 3.53 615
B.V.K. Lavania (India)	Treatment of Left Bank Slopes of Ichari Dam. 3.54 621
A.J.T. Gilchrist (United Kingdom)	Design and Construction of Geocell Mattress as Embankment Foundation. 3.56 627
N.H. Wade L.F. Wei L.R. Courage R.A. Keys (Canada)	Performance of an Earthdam and Cut-off Through Deep Alluvium. 3.57 635
K.B. Agarwal (India)	An Undrained Failure in the Foundation of an Earthdam. 3.58 645
J.R. Schneider R.W. Lindquist (USA) G.K. Sammy (West Indies)	Design and Performance of Arena Dam. 3.59 651
K.K. Kapoor S.C. Patodiya (India)	Case History of a Partially Underground Power House. 3.60 657
I.I. Corda (Romania)	Iron Gates II: Design and Performance of Dams— Geotechnical Considerations 3.63 663
St. Christoulas E. Gassios N. Kalteziotis G. Tsiambaos (Greece)	Slope Stability Problems Related to a Semi-Bridge Construction. 3.65 671
J.A. Posse R.P. Hermosilla J.M.M. Santamaria (Spain)	Monitoring of the Canales Dam and Its Control During Construction Period. 3.66 677
D.C. Cowherd V.G. Perlea A. Coulson (USA)	Performance of a Coal Refuse Embankment. 3.68 683



<i>Session III continued</i>		Page No.
R. Azevedo L.A. Santos (Brazil)	Field Observation and Finite Element Analysis of a Subway Excavation. 3.70	689
A. Marsland (England)	Failure of Flood Banks Due to Under Seepage. 3.72	695
J.D. Nelson (USA) B.P. Wrench (South Africa)	Construction of Road Embankments Over Very Soft Soils Using Band Drains and Preloading. 3.73	699
Izhar-ul-Haq (Pakistan)	Seepage Problems and Remedies—Hub Dam. 3.77	705
A.I. Harsulescu (Romania)	The Behaviour in Time of Ripa Albastra Dam Impervious Bentonitic Core. 3.78	711
F. J. Gichaga F.S. Atibu B.K. Sahu (Kenya)	Horizontal and Vertical Movements of Red Clay Highway Embankments. 3.79	717

Session IV

“Case Histories of Geotechnical Earthquake Engineering and Soil Dynamics”

Y. Koga O. Matsuo (Japan)	Stability Analysis of Seismically Damaged Embankments. 4.01	721
S. Chonggang (China)	Some Experiences from Damages of Embankments During Strong Earthquakes in China. 4.03	729
I. Rosenthal M. Itskowitch (Israel)	Vibration Response of Railway Bridge Piers to Nearby Pile Driving. 4.04	737
P. Fulan (China)	Theory and Experiment of Hammer Foundation Vibration. 4.05	743
T. Zhen-Yu T. Fang-Fu (China)	Stress Field Under a Reservoir and Its Induced Earthquake. 4.06	749
W. Xikang (China)	On Properties of Damping of Bases. 4.07	755
W. Xikang D. Shiwei Y. Xianjinan (China)	On Propagation of Elastic Surface Wave in Soil. 4.08	759



<i>Session IV continued</i>	Page No.
Q. Taiping L. HuiShan (China)	Influence of Piling on Characteristics of Liquefiable Soils. 4.10 765
W. Yuqing (China)	The Simplified Formulas for Predicting Seismic Liquefaction of Saturated Clayey Silt Site. 4.11 769
D. Shiwei (China)	The Effect of Foundation Shape on Dynamic Parameter of Bases. 4.12 773
L.S. Srivastava (India)	Landslides in Rock Slopes During January 19, 1975 Kinnaur Earthquake in Himachal Pradesh, India. 4.14 779
T.F. Wolff G.L. Hempen M.M. Dirnberger B.H. Moore (USA)	Probabilistic Analysis of Earthquake-Induced Pool Release. 4.15 787
M. Lew J.C. Bowman, Jr. (USA)	Case History of Seismic Base Isolation of a Building—The Foothill Communities Law and Justice Center. 4.16 795
K.V. Rodda C.W. Perry R.E. Tepel (USA)	Upgrading the Seismic Resistance of Stevens Creek Dam. 4.18 801
M.B. Ray D.K. Ghosh (India)	Seismic Response Analysis of Forebay Structure for C.W. Pump House of a Nuclear Power Project. 4.20 807
G. Maurath D. Amick (USA)	Characterization of Liquefaction Sites/Features in the Charleston, S.C. Area. 4.21 811
P. Kvasnicka T. Ivsic A. Kiricenko (Yugoslavia)	Analysis and Measurement of Foundation Vibrations at Two Compressor Stations in Yugoslavia. 4.23 819
A. Bapat (India)	Seismosedimentation and Lives of Reservoirs. 4.24 825
R.C. Lo W.G. Milne E.J. Klohn G.T. Handford (Canada)	Seismic Assessment of Syncrude Tailings Dyke. 4.26 829
S. Bandyopadhyay M.K. Gupta A.S. Arya (India)	Reliability of the Wave Equation Analysis in the Estimation of Static Bearing Capacity of Vertical Pile—a Case Study. 4.27 837



<i>Session IV continued</i>	Page No.
M.D. Gillon (New Zealand)	The Observed Seismic Behavior of the Matahina Dam. 4.29 841
P.S. Seco e Pinto (Portugal)	Soil Liquefaction Potential of a Highway Bridge Foundation. 4.31 849
P. Srinivasulu N. Lakshnaman K. Muthumani B.S. Sarma (India)	A Study of Dynamic Pile-Soil Interaction. 4.33 855
P.M. Byrne H. Vaziri U. Atukorala D. Fraser (Canada)	Model Tests on Seismic Stability of an Approach Fill Embankment, Annacis Island Bridge Project Vancouver, Canada. 4.34 863
V.D. Miglani (India)	In-Situ Determination of Dynamic Properties of Soil for Foundation of a Turbo-Generator. 4.36 871
F. Ciuffi (Italy)	Geotechnical Services for a Bridge in a Seismic Area. 4.40 877
Author Index.....	883



Volume II

Session V

"New Solutions to Traditional Geotechnical Problems [Case Histories]"

	Page No.
H. Grice E.T. Mosley R.M. Berry (USA)	Vertical Excavation Below Footing Solved by Compaction Grouting. 5.01 885
T.V. Nhiem (France)	Recent Examples of Cut and Fill Reinforcement on A41-Highway in France. 5.02 889
B. Wietek (Austria)	Drainage Walling as Excavation Support. 5.03 905
T.J. Lyman M.J. Robison D.S. Lance (USA)	Compaction and Chemical Grouting Phoenix Drain Tunnels. 5.04 911
R.P. Kummerle (USA) J.C. Dumas (Canada)	Soil Improvement Using Dynamic Compaction for the Bristol Resource Recovery Facility. 5.05 921
G.E. Blight (South Africa)	Effects of Collapse Settlement of Fill on Reinforced Earth Walls. 5.06 929
H.O. Chukweze (Nigeria)	Pavement Failure Caused by Soil Erosion. 5.10 935
T.B. Celestino O.A. Ferrari C.T. Mitsuse L.C. Dominique (Brazil)	Progress in the Use of NATM for the Sao Paulo Subway. 5.12 941
C. Mastrantuono A. Tomiolo E. Arcangeli (Italy)	Effectiveness of Sand Drains in Peaty Soil in a Case of Differential Settlement Recovering. 5.13 947
H. Meissner G. Borm (Germany)	Construction of a Double Tunnel with Ground Windows. 5.14 953
W. Yuqing Z. Weiquan Q. Taiping (China)	Evaluation of the Effect of Saturated Silty and Fine Sand Foundation Improved by Vibroflotation in Seismic Area. 5.15 963
B. Song (Korea) M. Gambin (France)	Dynamic Compaction—An Unusual Application. 5.16 969



<i>Session V continued</i>	Page No.
L.W. Franks J.M. Duncan S.A. Collins J. Fowler J.F. Peters V.R. Schaefer (USA)	Use of Reinforcement at Mohicanville Dike No. 2. 5.17 977
C.T. Yih R.P. Khera (USA)	Slurry Wall Instrumentation and Monitoring in Taipai. 5.18 985
L.D. Johnson (USA)	Deformation Behavior of Wilford Hall Hospital Mat. 5.19 989
J.E. Laier R.M. Mattox (USA)	Oversteepened Slopes Reinforced with Tensar Geogrid. 5.21 993
S.J. Kravits H.C. Harrel (USA)	Demonstrating Borehole Drilling Accuracy at the Navajo Dam. 5.23 997
S. DeFour A.S. Judge P. Lafleche (Canada)	Design and Monitoring of Earth Embankments over Permafrost. 5.25 1001
W. Schubert (Austria) T.L. Richardson (USA)	Soft Ground Tunneling on the Seoul Subway Using NATM. 5.27 1011
J.R. Davie M.R. Lewis L.W. Young (USA)	Accelerated Consolidation of Soft Clays Using Wick Drains. 5.29 1019
J.C. Neyer K.M. Swaffar H.R. Price (USA)	Tunnel Repair Using Cement-Stabilized Flyash. 5.30 1025
M.D. Boscardin (USA)	Impact of Tunneling on Two Brick-Bearing-Wall Structures. 5.31 1029
G. Guatteri (Brazil) J.L. Kauschinger (USA) A.C. Doria (Brazil) E.B. Perry (USA)	Advances in the Construction and Design of Jet Grouting Methods in South America. 5.32 1037



<i>Session V continued</i>	Page No.
W. Fan M. Shi Y. Qiu (China)	Ten Years of Dynamic Consolidation in China. 5.33 1047
N. Ghosh M.M. Tappa (England)	Experience in Ground Improvement by Dynamic Compaction and Preloading at Half Moon Bay—Saudia Arabia. 5.35 1055
R.L. Curtis V.E. Chouery-Curtis D.A. Miller (USA)	Geogrid Reinforced Soil Retaining Wall on Compressible Soil. 5.35 1063
R.D. Charles (USA)	Performance of Prefabricated Drains in Soft Soils. 5.36 1069
K.R. Darye M.R. Madhav (India)	Case Histories of Foundations with Stone Columns. 5.37 1075
D.J. Hardin M.L. Byington S.V. Mills (USA)	The Rehabilitation of Terminal 2—A Case History. 5.40 1087
B.R. Christopher A.B. Wagner (USA)	A Geotextile Reinforced Embankment for a Four Lane Divided Highway U.S. Hwy 45 West Bend, Wisconsin. 5.42 1093
T. Matsui K.C. San T. Amano Y. Otani (Japan)	Field Measurement on a Slope Cutting With Tensile Inclusions. 5.43 1099
D.L. Jones G.J. Macdonald M.H. Golder (United Kingdom)	The Performance Behaviour of a Grain Silo Foundtion in Jeddah Supported on Stone Columns. 5.44 1107
K.Y.C. Chung (USA)	Designing Geotextile Support for Submarine Power Cables. 5.45 1113
K.S.A. Rahim A.W. Dhowian (Saudi Arabia)	Foundations on Stone Columns Resting on Coral Limestone. 5.46 1117
D.A. Bruce F. Gallavresi (Italy)	Special Tunnelling Methods for Settlement Control: Infilaggi and Premilling. 5.48 1121
J. Paul (United Kingdom)	Reinforced Soil in the Repair of Embankment and Cutting Slip Failures. 5.51 1127



<i>Session V continued</i>	Page No.
M.L. Ohri A. Singh G.R. Chowdhary (India)	Distribution of Contact Pressure and Stresses Under Skirted Footings. 5.53 1133
D. Cazzuffi A. Pagotto. P. Rimoldi (Italy)	Behaviour of a Geogrid Reinforced Embankment Over Waste Material. 5.55 1137
E.R. Farrel T.L.L. Orr T. O'Donovan (Ireland)	Performance of LPG Storage Tanks on Ground Improved by Stone Columns. 5.56 1145
H.D. Sharma P. Kozicki (Canada)	The Use of Synthetic Liner and/or Soil-Bentonite Liner for Groundwater Protection. 5.61 1149
R.F. Reed P. Wright (USA)	Long Term Building Performance Over An Injected Subgrade. 5.64 1159
A.V. Shroff D.P. Amin D.L. Shah (India)	Epoxy Resin Grout System for Solutions to Traditional Geotechnical Problems. 5.66 1165

Session VI
"Case Histories of Soil Structure Interaction"

P.D. Long N. Van Quang (Vietnam) B. Berggren (Sweden)	Partial Underpinning of a Five-Storey Building. 6.02 1169
A. Ghinelli G. Vannucchi (Italy)	Damage to Masonry Structures in the Historic Center of Arezzo (Italy) Following the Excavation of Sewer Tunnel. 6.05 1173
A.H. Wu (USA)	Structural Damage Arrested by Stabilization of Landfill. 6.06 1179
R.B. Seed C.Y. Ou (USA)	Compaction-Induced Distress of a Long-Span Culvert Overpass Structure. 6.10 1183
L.W. Abramson W.H. Hansmire (USA)	Three Examples of Innovative Retaining Wall Construction. 6.11 1191
J.J. Grosch K.S. Al-Yahyai (Saudi Arabia)	Anchored Bulkhead Failure on the Arabian Gulf. 6.13 1201



<i>Session VI continued</i>		Page No.
R. Cameron C.A. Carr (Canada)	The Influence of Thin Clay Layers on the Design and Performance of a Flexible Cantilever Retaining Wall. 6.16	1209
S.I. Tsien (China)	Some Case Histories in Urban and Rural Geotechnical Engineering. 6.20	1219
W. Yiji (China)	Treatment of KARST Subgrade by Deep Drilled Pile Foundations. 6.24	1225
G.E. Barnes (United Kingdom)	Diagnosis of Structural Damage and Movement Due to More Than One Cause. 6.25	1229
M.R. Lewis M.M. Blendy (USA)	Pressure-Injected Footings—a Case History. 6.26	1233
V.K. Garga (Canada)	Anchor Failures at a Deep Excavation. 6.27	1239
S. Dovnarovitch Y. Ivanov (USSR)	The Failure of Oil Storage Tanks and Their Control. 6.28	1245
J.M. Keaveny P.M. Aas F. Nadim (Norway)	GBS Platform Evaluation Using Field Instrumentation. 6.29	1249
T.K. Kiu C. Soydemir M.P. Mitsch (USA)	Underpinning of an 11-Storey Building in Boston—A Case Study. 6.31	1257
R. Riker D. Dailer (USA)	Design, Construction, and Performance of a Deep Excavation in Soft Clay. 6.32	1263
A.V. Chummar (India)	Failure of an Oil Storage Tank. 6.33	1271
C.J.F.P. Jones (United Kingdom)	The Effects of Mining Subsidence on a Motorway Bridge. 6.35	1275
H.O. Chukweze (Nigeria)	Correlation Between the Actual and Predicted Settlements of Structures on Tropical Soil Foundation. 6.36	1279
X. Sheng-sun (China)	Bearing Capacity of Pile Foundation. 6.37	1285
J.K. Jain R.K. Khare (India)	Stress Analysis of Gravity Dam Founded on Rock Mass Having Horizontal Seam (A Case Study of Bargi Dam in Madhya Pradesh, India). 6.39	1289
W.B. Ferguson E.F. Glynn (USA)	A Foundation Failure in Philadelphia. 6.42	1293



<i>Session VI continued</i>	Page No.
R.J. Finno (USA) D.K. Atmatzidas (Greece) S.M. Nerby (USA)	Ground Response to Sheet Pile Installation in Clay. 6.43 1297
S.A. Bucher R.J. Krizek (USA) D.K. Atmatzidis (Greece)	Full-Scale Load Test of Caisson on Chicago Hardpan. 6.44 1303
J.R. Davie M.R. Lewis (USA)	Settlement of Two Tall Chimney Foundations. 6.45 1309
M.A. Gouda I.W. Lippincott D. Raghu (USA)	Distress to Structures on Loose Ash and Cinders Fills. 6.49 1315
N.P. Angeles U.W. Stoll (USA)	Design and Field Monitoring of 70-Foot High Tied Anchor Retaining Wall. 6.50 1319
D.P. Gado G.P. Kelley J.J. McElroy (USA)	Performance of Foundations and Retaining Structures. 6.51 1327
S. Hansbo (Sweden)	Common-Sense Foundation Design. 6.54 1337
S.S.M. Cheng S.A. Ahmad (Canada)	Dynamic Testing Versus Static Load Test: Five Case Histories. 6.55 1343
R.C. Hepworth J. Langfelder (USA)	Settlement and Repairs to Cement Plant in Central Utah. 6.56 1349
K.D. Tucker (USA)	Performance Evaluation of Pile Foundation Using CPT Data. 6.58 1355
D. Sharma (India)	Foundation Failure of the St. Thomas Church, New Delhi. 6.59 1365
Z.S. Zhang D.Z. Luan X.X. Zhang (China)	The Case Record of Ba-Yu-Quan Anchor Slab Retaining Wall. 6.60 1371
T.L. Cooling J.B. Hummert, Jr. (USA)	Drilled Pier Load Test, Fort Collins, Colorado. 6.61 1375



<i>Session VI continued</i>	Page No.
B.R. Christopher C.N. Baker, Jr. (USA)	Caisson Load Test and Instrumentation Program—Sohio Corporate Headquarters. 6.62 1383
C.N. Baker, Jr. S.B. Steinberg W. Lam (USA)	Building Design and Construction Over Organic Soil. 6.63 1389
M.R. Lewis J.R. Davie C.L. Weaver (USA)	Differential Settlement of Nuclear Power Plant Foundations. 6.64 1395
G. Hannink (The Netherlands)	Reconstruction of the Settlement History of Buildings. 6.67 1403
G. Hannink A.F. van Tol (The Netherlands)	Large Horizontal Displacements of Houses in Rotterdam. 6.68 1409
K.M. Chua L.J. Petroff (USA)	Predicting Performance of Large-Diameter Buried Flexible Pipe: Learning from Case Histories. 6.72 1417
J.C. Li H.L. Yao L.P. Shi B.I. Shy (Taiwan)	Behavior of Ground Anchors for Taipei Sedimentary Soils. 6.73 1421
A.J. Nicholson, Jr. J.R. Wolosick (USA)	Post-Tensioned Caissons Permit Interstate Construction: A Case History. 6.74 1425
A.S. Stipho (Saudi Arabia)	Model Test of Reinforced Earth Retaining Wall. 6.76 1433
S. Abdel-Salam M. Mashhour (Egypt)	Repair and Rehabilitation of a Residential Building at Nile River in Cairo. 6.77 1437
Y.S. Kim P.Y. Thompson (USA)	Behavior of Buried Concrete Box Culvert. 6.79 1443
R.H. Borden W.J. Sullivan W. Lien (USA)	Settlement Predictions in Residual Soils by Dilatometer, Pressuremeter and One-Dimensional Compression Tests: Comparison with Measured Field Response. 6.83 1449
M.P. Luong (France)	Collapsing Peak up of a Large Highway Steel Pipe-Arch. 6.88 1455
A. Kropp (USA)	Existing Pile Load Capacity Evaluation. 6.89 1471



<i>Session VI continued</i>	Page No.
R. Azevedo N. Consoli (Brazil)	Comparisons Between Field and Analytical Behavior of an Experimental Excavation. 6.90 1465
D.C. Cowherd S.M. Thrasher V.G. Perlea J.O. Hurd (USA)	Actual and Predicted Behavior of Large Metal Culverts. 6.92 1471
E.A. Nowatzki (USA) B.P. Wrench (South Africa)	Geotechnical Investigation into Causes of Failure of a Gabion Retaining Wall. 6.96 1477
S.V. Nathan (USA)	Two Case Histories: Performance of Shallow Foundations on Sand. 6.97 1483
P.K. Jain B. Singh G.C. Nayak (India)	Geotechnical Studies of Foundation of a Tilted Tank at Parikshatgarh, India. 6.98 1489
R.J. Rapp J.S. Schwenk (USA)	Lock and Dam No. 26 R, Lock Cofferdam, Construction Sequencing. 6.99 1495
X.H. Zhao Y.A. Yin Y.P. Qian J.G. Dong W.Y. Shen (China)	A Study of 15 Cases of Soil-Structure Interaction in China. 6.100 1501
I. Houssamy M.M. Daman (USA)	Simulation of Drilled Pier Behavior Under Three-Dimensional Loading. 6.101 1505
G. Ranjan S.K. Kaushik V.K. Gupta (India)	Health of Ammonia Horton Spheres and Foundations—a Case Study. 6.102 1509



State-of-the-Art Papers

	Page No.
B.B. Broms (Singapore)	Design and Construction of Anchored and Strutted Sheet Pile Walls in Soft Clay. 1515
C.S. Desai (USA)	Case Studies Through Material Modelling and Computation. 1551
G.F. Sowers (USA)	Movement in the Powerhouse Excavation Saguling Project, Indonesia. 1567
J. Ramage (USA)	Lipari Landfill: Lechate Containment System—Geotechnical Considerations. 1577
W.D.L. Finn (Canada)	Case Histories in Seismic Response Analysis. 1585
G.W. Clough (USA)	Review of River Bank Stability Processes in Stabilizing Measures. 1597
M.L. Silver* (USA)	Lessons Learned from Case History Performance of Earth Dams, Embankments and Natural Slopes.
Author Index 1609

*To be printed in Volume III



Volume III

	Page No.
Preface	iii
Organizing Committee	xxix
Program	xxxix
Opening Remarks	xxxv
Photographs	xxviii
List of Participants	xlv
Concluding Remarks	lv
Banquet Speeches	lvi

Session I

"Case Histories of Geotechnical and Hydrological Management of Solid, Hazardous, and Radioactive Wastes"

dr.ir M. Loxham (Netherlands)	General Report	1613
----------------------------------	----------------------	------

Session II

"Case Histories in Geological Engineering and Rock Mechanics"

B.B. Broms Y.S. Lau (Singapore)	Failure of a Transport Tunnel Below a Dolomite Stockpile. 2.09	1619
R.K. Bhandari (India)	General Report	1627
	Discussion and Replies	1633

Session III

"Case Histories of Dams, Embankments, and Slopes"

State-of-the-Art Paper

M.L. Silver R. Riccioni (USA)	Lessons Learned from Case History Performance of Earth Dams, Embankments, and Natural Slopes.	1639
-------------------------------------	---	------



Contributed Papers

Y. Tanabashi H. Ochiai Y. Saitoh K. Yasuhara (Japan)	Case Studies on Long-Term Settlement of Soft Clay Ground. 3.23	1655
S.K. Mahdi (Pakistan)	Tarbela Reservoir A Question of Induced Seismicity. 3.49	1663
C.R. Gangopadhyay R.A. Anderson (USA)	The Failure and the Remedial Construction of a Containment Dike on a Lacustrine Clay. 3.75	1669
C.L. McAnear G.P. Hale (USA)	General Report	1675
	Discussions and Replies	1677



Session IV
"Case Histories of Geotechnical Earthquake Engineering and Soil Dynamics"

	Page No.
A.S. Arya S. Saran S. Bandyopadhyay (India)	Dynamic Response of An Actual Hammer Foundation. 4.28 1681
S. Kumar (India)	Dynamic Cross Interaction Effect on a Compressor Foundation on Piles. 4.30 1687
A.P. Davis G. Castro S.J. Poulos (USA)	Strengths Backfigured from Liquefaction Case Histories. 4.35 1693
V.K. Puri (USA)	Observed and Predicted Natural Frequency of a Pile Foundation. 4.41 1703
S. Saxena (USA)	General Report 1707
	Discussion and Replies 1711



Session V
"New Solutions to Traditional Geotechnical Problems [Case Histories]"

K.R. Darye (India)	General Report	1717
-----------------------	----------------------	------

Session VI
"Case Histories of Soil Structure Interaction"

R.E. Olson K. Al-Shafei (USA)	Axial Load Capacities of Steel Pipe Piles in Sand. 6.47	1731
J.G. Zeitlen (Israel)	Stiffening Cast-in-Place Piling by Bottom Grouting. 6.78	1739
R.F. Wilson-Fahmy (Egypt)	A Soil-Structure Interaction Analysis of a Damaged Building. 6.93	1745
W. Akili (Qatar)	Driven Pile Foundations in Coral Sand, Jeddah, Saudi Arabia. 6.94	1749
S. Prakash K. Sreerama Sally Prakash (USA)	Predictions and Performance of Piles under Static and Dynamic Loads. 6.103	1757
P.E.F. Ciuffi (Italy)	Settlements in a Masonary Villa Caused by Trees. 6.104	1763
G. Mesri D.O.K. Lo K. Karlsrud (USA)	ILLICON Analysis of Ellingsrud Test Fill. 6.105	1765
S.V. Nathan (USA)	General Report	1771
	Discussion and Replies	1777
	Author and Discussor Index	1787